

## **RISK ASSESSMENT INSPECTION REPORT**

Made on 28 September 2024 by Richard Daniel and Joanne Sears

Presented to Stillingfleet Parish Council on the 3 October 2024.

### **THE GREEN**

	<b>Problem (if any)</b>	<b>Recommended Action</b>
Trees	Low branches at eye level on Plane Tree near Harmony House	Light pruning completed by volunteers
Walls / fences / hedges	None identified	
Manhole covers	None identified	
Drain outlets	None identified	
Effluent leaks	None identified	
Dog Poo	None observed	
Noticeboards x 3	Unusable Rotten noticeboard on wall outside village institute	PC/VI noticeboard being replaced – quote accepted. Replacement of village notice board (by the bridge) under consideration
Other Stuff		

**NOTE – The playground equipment is subject to a separate risk assessment and safety inspection undertaken every two weeks and an annual inspection by a ROSPA qualified specialist**

Updated 4/2/2024

## THE PARISH FIELD

	<b>Problem (if any)</b>	<b>Recommended Action</b>
Fences and gates	None identified	
Trees	None identified	

## PERMANENT STRUCTURES

	<b>Problem (if any)</b>	<b>Recommended Action</b>
Street lights	Severe lean on electric pole outside No. 4 Cawood Road	Contacted Northern Powergrid requesting corrective action
Bus shelters	None identified	
Benches	None identified	
Waste bins	None identified	
Footbridges	None identified	
Pavements	Trip hazard marked Post Office Telephones on the corner outside Ridegfield Escrick Road	Contacted British Telecom requesting corrective action. Ref MY-MY1478391
Telephone kiosk	The telephone kiosk on York Road Stillingfleet is in a dilapidated state consistent with its age of some 85 or 90 years. The door and its hinges seem sound.	Asset has been sold – no longer owned by the PC. Asset expected to be removed autumn 2024 with

	<p>On the right hand side (from the road) there are two small broken panes measuring 6"x2 1/2 "</p> <p>On the left hand side there is one broken pane 6" x 2 1/2".</p> <p>At the front there is one missing pane 6" x 12". The remaining panes are all plastic except for the top pane.</p> <p>The kiosk has been leaning slightly to the left for at least 40 years without any sign of progressive movement. It is believed to be approximately 2" to 3" out of vertical and quite stable.</p>	<p>electric connection made safe and site restored to verge.</p>
--	--	--