## RISK ASSESSMENT INSPECTION REPORT

Made on 14 May 2023 by Richard Daniel and Joanne Sears Presented to Stillingfleet Parish Council on the 18 May 2023.

#### THE GREEN

Problem (if any)	Recommended Action
None	
Vegetation growing across footpath at Yew Tree House making it very difficult for mobility scooter to use footpath	Cllr Foy to ask owners to address
None	
None	
None	
None found	
None	
None	
Stones on verges of Green create a trip hazard	Reminder posted in Parish Magazine that owners are liable for any resulting accident claim.
Potholes on the road bordering the Green – some	Letter to NYC Highways
	None  Vegetation growing across footpath at Yew Tree House making it very difficult for mobility scooter to use footpath  None  None  None  None  None  None  Stones on verges of Green create a trip hazard

# NOTE – The playground equipment is subject to a separate risk assessment and safety inspection undertaken every two weeks

# THE PARISH FIELD

	Problem (if any)	Recommended Action
Fences and gates	None	
Trees	Tree fallen across the public footpath and the beck in the ByeLaw Charity Field	Drainage Board have removed

## PERMANENT STRUCTURES

	Problem (if any)	Recommended Action
Street lights	None	
Bus shelters	None	
Benches (inc Jubilee bench)	None	
Waste bins	None	
Footbridges	Footbridge along beckside too narrow	Replaced with new bridge
Pavements	None	
Telephone kiosk	Broken glass in a small pain	Protect with tape

The telephone kiosk on York Road Stillingfleet is in a dilapidated state consistent with its age of some 85 or 90 years.

The door and its hinges seem sound.

On the right hand side (from the road) there are two small broken panes measuring 6"x2 1/2 "

On the left hand side there is one broken pane 6" x 2 1/2".

At the front there is one missing pane 6" x 12". The remaining panes are all plastic except for the top pane.

The kiosk has been leaning slightly to the left for at least 40 years without any sign of progressive movement. It is believed to be approximately 2" to 3" out of vertical and quite stable.

Long term either full restoration (dependent upon raising funds) or disposal